

Lot No.	DP No.		House No.	y=.	Boundary Trap	AAV	Air Admitance Valve	BS	Sink (bar)	Chr	Chamber
Street	Giren St			A):	Inspection Shaft	В	Basin	(L)	Trough (laundry)	-	Pit
SUBURB OF	Tamworth			-35-	Inspection Opening	Bth	Bath Waste	WC	Water Closet	G	Grease Interceptor
LGA	lanworth			ORG	Gully	Bld	Bidet	Vert	Verticat Pipe	·	Pump Unit
Licence No.	2597110			N	FW	co	Clean Out	⋰ws	Waste Stack	ors	Onsite Treatment System
SCALE			SSD No.	. 2	Vertical Junction	FW	Floor Waste Gully	SVP	Sewer Vent Pipe	. ▶ R	Reflux Valve
Now / COC No.		11	Date 23/11/2023		Stoped Junction	Shr	Shower	√V	Vent Pipe		Capped Point
			• •	4.	On Back Junction	S	Sink (kitchen)	IPMF	Induct Pipe Mica Flap	Prov	Provisional (future) drain point

Signature:__

This diagram was supplied by the plumber/drainer whose licence number appears above. NOTES: •

It has been drawn to show the approximate location of the private sewerage service pipes and may not be accurate.

Any broken/dashed lines denote the assumed (not verified) position of private sewerage services.

Further acceptable abbreviations may be used as identified in AS/NZS 3500.2.2003 Sanitary Plumbing and Drainage Table 6.1 and Fair Trading's Sewer Service Diagram Requirements document. © State of New South Wales through NSW Fair Trading April 2014